

REPWIRE LLC 5500 NW 106Court Doral FL 33178 Date: 2015/06/17

Subscriber: None

PartySite:

File No:

Service Request No: 2589118 Project Number: 15SR2589118

PD No: 15M25441

PO Number:

Subject: Listing Correlation Sheet

Enclosed is a copy of your completed Listing Correlation Sheet covering the Basic File listed below. The following documents were added (new) or revised on 06/17/2015.

File Pages
E476839 Cert of Compliance

Revised

New

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at http://www.ul.com/global/eng/pages/corporate/contactus.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above, referring to the above Service Request number.

This material is provided on behalf of UL LLC(UL) or any authorized licensee of UL.

NBK File

CERTIFICATE OF COMPLIANCE

 Certificate Number
 20150617-E476839

 Report Reference
 E476839-20150604

Issue Date 2015-JUNE-17

Issued to: REPWIRE LLC

5500 NW 106 Ct Doral, FL 33178

This is to certify that THERMOSET-INSULATED WIRE

representative samples of Models RHH, RHW, RHW-2, XHH, XHHW, XHHW-2

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 44 - Thermoset-Insulated Wires and Cables Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC



